

基隆市天外天垃圾資源回收(焚化)廠

異味監測結果

| 年月份 \ 項目 |   | 廠址周界      |           |           | 培德路<br>(東信路至深澳坑路段) |           |           | 培德路<br>(東峰街至港平新村段) |           |           | 深澳坑路<br>(港平新村至深澳國小段) |           |           |
|----------|---|-----------|-----------|-----------|--------------------|-----------|-----------|--------------------|-----------|-----------|----------------------|-----------|-----------|
|          |   | 異味<br>(早) | 異味<br>(中) | 異味<br>(晚) | 異味<br>(早)          | 異味<br>(中) | 異味<br>(晚) | 異味<br>(早)          | 異味<br>(中) | 異味<br>(晚) | 異味<br>(早)            | 異味<br>(中) | 異味<br>(晚) |
| 115      | 1 | ●         | ●         | ●         | ●                  | ●         | ●         | ●                  | ●         | ●         | ●                    | ●         | ●         |
|          | 2 | ●         | ●         | ●         | ●                  | ●         | ●         | ●                  | ●         | ●         | ●                    | ●         | ●         |
|          | 3 | ●         | ●         | ●         | ●                  | ●         | ●         | ●                  | ●         | ●         | ●                    | ●         | ●         |
|          | 4 | ●         | ●         | ●         | ●                  | ●         | ●         | ●                  | ●         | ●         | ●                    | ●         | ●         |
|          | 5 | ●         | ●         | ●         | ●                  | ●         | ●         | ●                  | ●         | ●         | ●                    | ●         | ●         |
|          | 6 | ●         | ●         | ●         | ●                  | ●         | ●         | ●                  | ●         | ●         | ●                    | ●         | ●         |

註:1. 周界排放標準為50

2. ●為無法聞出(異味污染物濃度小於10)

3. 監測單位：中環科技事業股份有限公司

4. 監測項目：異味污染物；監測方法：NIEA A201.14A